
BLK BOX BLACKOUT SQUAT STAND - 2.2M

21-0113-0E



PRODUCT SPECIFICATION

	PRODUCT WEIGHT	-	55kg
	MAX USER WEIGHT	-	125kg
OWNERS MANUAL & QUICK START GUIDE	MAX USER	-	1
	MAX TRAINING WEIGHT	-	350kg
NOTE: PLEASE READ ALL THE INSTRUCTIONS	DIMENSIONS	-	1112mm x 1320mm x 2266mm
CAREFULLY BEFORE ASSEMBLING THIS PRODUCT.	SAFE WORKING ZONE	-	2312mm x 2820mm x 3076mm

BLK BDX #MADEINBELFAST

WARNING

SERIOUS OR FATAL INJURIES MAY OCCUR FROM INCORRECTLY ASSEMBLED EQUIPMENT. ALWAYS ENSURE BOLTS ARE TIGHTENED CORRECTLY AND ALL PARTS ARE LEVEL AND PLUMB. TO FURTHER REDUCE RISK OF INJURIES OR DEATH PLEASE USE OUR SUGGESTED TOOLS AND PERSONAL PROTECTIVE EQUIPMENT (PPE). WE SUGGEST THAT A MINIMUM OF THREE PEOPLE ARE INVOLVED IN THE ASSEMBLY OF THIS PRODUCT. EACH PERSON SHOULD BE EQUIPPED WITH SAFETY GLASSES, STEEL TOE CAP BOOTS AND EAR PLUGS.

PLEASE BE AWARE OF THIS SYMBOL AS AN INDICATION TO CHECK THAT A PART IS LEVEL OR PLUMB.



THIS SYMBOL IS AN INDICATION OF THE RECOMMENDED TORQUE EACH BOLT SHOULD BE TIGHTENED TO. THIS VALUE WILL BE DEPENDENT ON THE BOLT TYPE. PLEASE HAND TIGHTEN ALL BOLTS UNTIL YOU SEE THIS SYMBOL.




TOOLS REQUIRED



No.	Name	SKU	ŌТY
1	UPRGIHT 2.2M	21-0573	2
2	BASE FRAME - SA	21-0572	2
3	1.2 SINGLE BAR	21-0015	1
4	BACK CM	21-0602	1
5	FOOT PLATE	20-0412	2
6	BRACE PLATE	20-0472	4
7	M10X90 HEX HEAD BOLT	10-0008	20
8	M10 WAHER	10-0019	42
9	M10 NYLOCK NUT	10-0024	20
10	J-HOOK (PAIR)	16-0001	1
11	SLEEVE ANCHOR	10-0031	2

PARTS & ATTACHMENTS



ASSEMBLY




BOLT 10TY BACK CM (21-0602) AND 20TY BASE FRAME (21-0572) WITH BOLTS ASSEMBLY AS SHOWN.





INSERT 10TY UPRIGHT (21-0573) INTO SLOT ON BASE FRAME (21-0572) AND ATTACH USING 20TY BRACE PLATE (20-0472) AND BOLT ASSEMBLIES AS SHOWN. ATTACH 1 0TY FOOT PLATE (20-0412) USING BOLT ASSEMBLIES AS SHOWN. REPEAT FOR OPPOSITE SIDE.




3

PLACE 10TY 1.2 SINGLE BAR (21-0015) AT PREFERRED HEIGHT ATTACH WITH BOLT ASSEMBLIES AS SHOWN.

FOLLOW GUIDE BELOW FOR FLOOR MOUNTING.

TIGHTEN ALL BOLT ASSEMBLIES TO 30NM.



-DRILL 10MM HOLE, 90MM DEEP USING PLATE AS A GUIDE. -VACUUM OUT THE DUST. -HAMMER SLEEVE ANCHOR INTO THE HOLE. -TIGHTEN SLEEVE ANCHOR TO

-TIGHTEN SLEEVE ANCHOR SPECIFIED TORQUE USING 13MM SPANNER.